Classifying the Entire Service Line When Ownership Is Split

Purpose of this worksheet: To summarize EPA's requirements for classifying the entire service line when ownership is split.

Introduction

Lead Status Unknown

In many cases, service line ownership is **split** meaning that the system owns a portion and the customer owns a portion of the service line. Exhibit 1 below is a diagram of a possible division in service line ownership between the water system and customer. While the LCRR requires the inventory to categorize each service line or portions of the service line where ownership is split, a single classification per service line is also needed to support various LCRR requirements, such as lead service line replacement (LSLR), tap sampling, and risk mitigation. Table 1 below indicates how to classify the material for the entire service line when ownership is split between the water system and customer. For more information, see EPA's, *Guidance for Developing and Maintaining a Service Line Inventory* (2022).




Table 1: Classification of Entire Service Line When Ownership is Split **System-Owned Portion** Classification for Entire Service Line **Customer-Owned Portion** Lead Lead Lead Lead Galvanized Requiring Replacement Lead Lead Non-lead Lead Lead Status Unknown Lead Lead Non-lead Lead Lead Non-lead and never previously lead Non-lead, specifically galvanized pipe material Non-lead Non-lead, material other than galvanized Non-lead Non-lead Lead Status Unknown Lead Status Unknown Non-lead Non-lead, but system is unable to demonstrate Galvanized Requiring Replacement Galvanized Requiring Replacement it was not previously Lead Lead Status Unknown Lead Lead Galvanized Requiring Replacement Lead Status Unknown Galvanized Requiring Replacement Lead Status Unknown Non-lead Lead Status Unknown

Lead Status Unknown

Lead Status Unknown

Source: Exhibit 2-3 of Guidance for Developing and Maintaining a Service Line Inventory (USEPA, 2022).

PWS Information

Purpose of this worksheet: For water systems to document basic system information.

Facility Information			
Water System Name:			
DIXON, TOWN OF			
PWSID:	Population Served (number of people):	Number of Service Connections:	PWS Type:
083090034	216	88	✓ CWS
If you are a CWS, do multi-family resid	lences comprise at least 20% of the stru	ictures you serve?	No
Mailing Address			
Street or P.O. Box:			
PO BOX 38			
City or Town:		State:	Zip Code:
Pablo		мт	59855
System Contact Person			
Name:		Title:	
Raquel Davis		Water and Sewer Operations Manage	er
Telephone:		Email:	
406-675-4491		rjdavis@skha.org	
Person Who Prepared Inventory (if d	ifferent from above)		

PWS Name: DIXON, TOWN OF

PWSID: 083090034

Date Last Updated: 10/14/2024

Purpose of this worksheet: To provide a customizable format water systems can use to track materials for each service line in their distribution system.

	Loc	cation Informat	ion					System	n-Owned Portion						
Unique Service Line ID	Location Id Street Address	entifier Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Verif Describe the Field Verification Method	ed: Enter the Date of	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date
A Unique ID is recommended for each service line.	Water systems must track of lines in their internal inver accessible version, location id lead and galvanized requirit system does not use addrest identifier, other options coordinates, landmark, interdetails to specify servi	ntory. For the publicly entifiers are required for ng replacement. If the sses for their location could include GPS section, block, or other	Select Yes if sensitive subpopulation, e.g., day care, school, multifamily home. If Yes-Other, describe in the Notes field.	Does location meet state affordability guidelines or other measures?	Dropdown list includes recommended subclassifications. If "Non-Lead Other", describe in Notes field	Select Yes, No, or Don't know. Important for determining if downstream/ customer- owned galvanized service line requires replacement	Date, year, or estimated date range when the service line was installed or replaced	Diameter in inches	Select option from drop down list. If "Other," describe in the Notes field	Select Yes or No	Select option from drop down list. If "Other," describe in the Notes field	Enter approximate date of field verification or date that the record was updated	Can use this field for documenting additional relevant information, including when classification changes.	Dropdown list includes recommended subclassifications. If non- lead other, describe in Notes field.	Date, year, or estimated date range when the service line was installed or replaced
11814385	10 5TH ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814420	10 A ST, DIXON, MT 59831		No	No	Non-Lead - Other	No	2021		Installation date after lead ban	No				Non-Lead - Other	2021
11814376	105 B ST, DIXON, MT 59831		No	No	Non-Lead - Other	No	2002		Installation date after lead ban	No				Non-Lead - Other	2002
11814415	109 4TH ST, DIXON, MT 59831		Yes - Other	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814455	10954 MT HWY 200, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814440	11 SELOW CREEK RD, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1938			No				Unknown - Material Unknown	1938
11814372	112 B ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1972			No				Unknown - Material Unknown	1972
11814426	116 HWY 200 A ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814422	12 A ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1974			No				Unknown - Material Unknown	1974
11814456	121 B ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814441	124 B ST, DIXON, MT 59831		No	No	Non-Lead - Other	No	2006		Installation date after lead ban	No				Non-Lead - Other	2006
11814390	124 EAST ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know			1000 0011	No				Unknown - Material Unknown	
11814411	125 2ND ST, DIXON, MT 59831		Yes - Other	No	Unknown - Material Unknown	Don't Know	1920			No				Unknown - Material Unknown	1920
11814436	125 A ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	

PWS Name: DIXON, TOWN OF PWSID: 083090034

Date Last Updated: 10/14/2024

Purpose of this worksheet: To provide a customizable format water systems can use to track materials for each service line in their distribution system.

	Lo	cation Informati	ion					System	-Owned Portion						
Unique Service Line ID	Location lo Street Address	dentifier Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Verif Describe the Field Verification Method	ed: Enter the Date of	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date
11814416	125 A ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814380	132 B ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1910			No				Unknown - Material Unknown	1910
11814374	133 EAST ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1910			No				Unknown - Material Unknown	1910
11814421	14 A ST, DIXON, MT 59831		No	No	Non-Lead - Other	No	2021		Installation date after lead ban	No				Non-Lead - Other	2021
11814383	143 B ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1929			No				Unknown - Material Unknown	1929
11814386	144 B ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1910			No				Unknown - Material Unknown	1910
11814435	145 EAST ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814461	147 A ST, DIXON, MT 59831		Yes - Other	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814407	15 5TH ST #A, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814406	15 5TH ST #B, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814381	15 SELOW CREEK RD, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1972			No				Unknown - Material Unknown	1972
11814425	16 4TH ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1920			No				Unknown - Material Unknown	1920
11814419	16 A ST, DIXON, MT 59831		No	No	Non-Lead - Other	No	2021		Installation date after lead ban	No				Non-Lead - Other	2021
11814446	17 4TH ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1949			No				Unknown - Material Unknown	1949
11814410	17 A ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1978			No				Unknown - Material Unknown	1978
11814464	18 A ST, DIXON, MT 59831		No	No	Non-Lead - Other	No	2021		Installation date after lead ban	No				Non-Lead - Other	2021
11814433	2 A ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1978			No				Unknown - Material Unknown	1978
11814437	20 5TH ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	

PWS Name: DIXON, TOWN OF PWSID: 083090034

Date Last Updated: 10/14/2024

Purpose of this worksheet: To provide a customizable format water systems can use to track materials for each service line in their distribution system.

	Lo	ocation Informati	ion					System	n-Owned Portion						
Unique Service Line ID	Location Id	dentifier Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Verif Describe the Field Verification Method	ed: Enter the Date of	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date
11814424	20 A ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814378	20 WEST ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1978			No				Unknown - Material Unknown	1978
11814417	203 A ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814412	207 A Street Lot 17 & 17 A, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814392	208 B ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814449	212 B ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814454	217 A ST, DIXON, MT 59831		No	No	Non-Lead - Other	No	1990		Installation date after lead ban	No				Non-Lead - Other	1990
11814423	22 A ST, DIXON, MT 59831		No	No	Non-Lead - Other	No	2021		Installation date after lead ban	No				Non-Lead - Other	2021
11814457	23 A ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814399	25 A ST, DIXON, MT 59831		No	No	Non-Lead - Other	No	2022		Installation date after lead ban	No				Non-Lead - Other	2022
11814400	26 A ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814401	27 A ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814402	28 A ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814403	29 A ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814396	3 SELOW CREEK RD, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814413	30 2ND ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814404	30 A ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814438	301 B ST, DIXON, MT 59831		No	No	Non-Lead - Other	No	1990		Installation date after lead ban	No				Non-Lead - Other	1990

PWS Name: DIXON, TOWN OF PWSID: 083090034

Date Last Updated: 10/14/2024

Purpose of this worksheet: To provide a customizable format water systems can use to track materials for each service line in their distribution system.

	Lo	cation Informat	ion					System	-Owned Portion						
Unique Service Line ID	Location Id	dentifier Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	Veri	Enter the Date of	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date
11814394	303A Street, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814444	304 B ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1987			No				Unknown - Material Unknown	1987
11814428	308 B ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1986			No				Unknown - Material Unknown	1986
11814405	309 B ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1914			No				Unknown - Material Unknown	1914
11814382	311 A ST, DIXON, MT 59831		No	No	Non-Lead - Other	No	1994		Installation date after lead ban	No				Non-Lead - Other	1994
11814387	312 B ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814375	316 B ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1924			No				Unknown - Material Unknown	1924
11814379	321 B ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1970			No				Unknown - Material Unknown	1970
11814445	323 B ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814443	328 B ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1920			No				Unknown - Material Unknown	1920
11814418	35 B ST & 3rd ST, DIXON, MT 59831		Yes - Other	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814430	35 EAST ST, DIXON, MT 59831		No	No	Non-Lead - Other	No	1994		Installation date after lead ban	No				Non-Lead - Other	1994
11814451	37 B ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814431	4 A ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1965			No				Unknown - Material Unknown	1965
11814395	4 SELOW CREEK RD, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814389	405 C ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814442	409 A ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1972			No				Unknown - Material Unknown	1972

PWS Name: DIXON, TOWN OF PWSID: 083090034

Date Last Updated: 10/14/2024

Purpose of this worksheet: To provide a customizable format water systems can use to track materials for each service line in their distribution system.

	Lo	cation Informati	ion					System	n-Owned Portion						
Unique Service Line ID	Location Ic Street Address	dentifier Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Verifi Describe the Field Verification Method	ed: Enter the Date of	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date
11814373	411 B ST, DIXON, MT 59831		Yes - School	No	Non-Lead - Plastic	Yes	2024	1½"	Service line repair or replacement record	Yes	Mechanical excavation at one location	6/30/2024	There was a leak at the meter and when it was opened up it was discovered a lead service line. The both sides of the meter was replaced with poly.	Unknown - Material Unknown	2024
11814460	421 A ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814462	429 C ST, DIXON, MT 59831		No	No	Non-Lead - Other	No	2017		Installation date after lead ban	No				Non-Lead - Other	2017
11814398	45 B ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1972			No				Unknown - Material Unknown	1972
11814397	45 B ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1972			No				Unknown - Material Unknown	1972
11814447	5 PRIDDY LN, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1916			No				Unknown - Material Unknown	1916
11814384	505 C ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1910			No				Unknown - Material Unknown	1910
11814458	525 B ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814409	529 A ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814459	541 B ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814432	6 A ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814450	7 A ST, DIXON, MT 59831		No	No	Non-Lead - Other	No	1999		Installation date after lead ban	No				Non-Lead - Other	1999
11814434	8 A ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814448	8 B ST, DIXON, MT 59831		No	No	Non-Lead - Other	No	1997		Installation date after lead ban	No				Non-Lead - Other	1997
11814391	8 SELOW CREEK RD, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know	1986			No				Unknown - Material Unknown	1986
11814414	9 A ST, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	

	Detailed Inventory
PWS Name: DIXON, TOWN OF	
PWSID: 083090034	
Date Last Updated:	10/14/2024

Purpose of this worksheet: To provide a customizable format water systems can use to track materials for each service line in their distribution system.

	Lo	cation Informati	on					System	-Owned Portion						
Unique Service Line ID	Location Id		Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	Veri	Enter the Date of	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date
11814452	9 B ST, DIXON, MT 59831		No	No	Non-Lead - Other	No	1988		Installation date after lead ban	No				Non-Lead - Other	1988
11814463	9 PRIDDY LN, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814408	9 SELOW CREEK RD, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814393	A Street, DIXON, MT 59831		No	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	
11814427	Corner of East and B Street, DIXON, MT 59831		Yes - Other	No	Unknown - Material Unknown	Don't Know				No				Unknown - Material Unknown	

	Select option from drop down list. If Select Yes or No Select option from drop down list. If "Other," describe in the Notes field that rec						Other Pot	ential Source	s of Lead	Additio	nal Information	n to Assign Tap Monitoring Tie	ring	Lead Serv Replaceme	
Service Line Size		Line Material	Veri Describe the Field		Notes	Entire Service Line Material Classification	is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead Solder Installed Before Your State's Lead Ban (Generally 1986 - 1988)?	Current LCR Sampling Site?	Date of System- owned LSLR	Date of Customer- owned LSLR
Diameter in inches	"Other," describe in	Select Yes or No	drop down list. If "Other," describe in	Enter approximate date of field verification or date that record was updated	Can use this field for documenting additional relevant information, including when classification changes.	Dropdown list includes four required service line classifications of Lead, Non-lead, Galvanized Requiring Replacement, or Unknown	For example, lead gooseneck or pigtail where the water main is connected to the service line	Select Yes, No, or Don't Know	For example, backflow preventer or meter containing lead	Note: This info	rmation may be hel _l	oful for identifying lead tap monitoring	ocations.		
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
	Installation date	No				Non-Lead	No	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Building	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Non-Lead	No	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Building	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			

	Customer-O	Enter the Date of Field Verification No No No No No No No No No					Other Pot	ential Source	s of Lead	Additio	nal Information	n to Assign Tap Monitoring Tie	ring	Lead Ser Replacem	
Service Line Size	Basis of Material Classification	Line Material	Ver Describe the Field	ified: Enter the Date of	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead Solder Installed Before Your State's Lead Ban (Generally 1986 - 1988)?	Current LCR Sampling Site?	Date of System- owned LSLR	Date of Customer- owned LSLR
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
	Installation date after lead ban	No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Building	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
	Installation date after lead ban	No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			

	Customer-C	Line Material Field Verified? Describe the Field Verification Method No No No No No No No No No					Other Pot	ential Source	s of Lead	Additio	nal Information	to Assign Tap Monitoring Tie	ering		rvice Line ent (LSLR)
Service Line Size	Basis of Material Classification	Line Material	Ver Describe the Field	ified: Enter the Date of	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead Solder Installed Before Your State's Lead Ban (Generally 1986 - 1988)?		Date of System- owned LSLR	Date of Customer- owned LSLR
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
	Installation date after lead ban	No				Non-Lead	No	Don't Know		Single Family Residence	Unknown	Unknown			
	Installation date after lead ban	No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
	Installation date after lead ban	No				Non-Lead	No	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
	Installation date after lead ban	No				Non-Lead	No	Don't Know		Single Family Residence	Unknown	Unknown			

	Customer-C	Classification Line Material Field Verified? Describe the Field Verification Method No No No No No No No No No					Other Pot	ential Source	s of Lead	Additio	nal Information	n to Assign Tap Monitoring Tie	ring	Lead Ser Replacem	
Service Line Size	Basis of Material Classification	Line Material	Ver Describe the Field	ified: Enter the Date of	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Service Line that	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead Solder Installed Before Your State's Lead Ban (Generally 1986 - 1988)?	Current LCR Sampling Site?	Date of System- owned LSLR	Date of Customer- owned LSLR
		No	Verification Method	Field Verification		Unknown	Don't Know	Don't Know	Contain Lead	Single Family	Unknown	Unknown			
						Unknown	Don't Know	Don't Know		Residence Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
	Installation date after lead ban	No				Non-Lead	No	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Building	Unknown	Unknown			
	Installation date after lead ban	No				Non-Lead	No	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence Single Family	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Residence Single Family	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Residence Single Family	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			

	Customer-Owned Portion						Other Potential Sources of Lead			Additio	Lead Service Line Replacement (LSLR)				
Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?		e Material Was Field ified: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead Solder Installed Before Your State's Lead Ban (Generally 1986 - 1988)?	Current LCR Sampling Site?	Date of System- owned LSLR	Date of Customer- owned LSLR
1½"	Service line repair or replacement record	No	Mechanical excavation at multiple locations	6/30/2024	There was a leak at the meter and when it was opened up it was discovered a lead service line. The both sides of the meter was replaced with poly.	Unknown	Don't Know	Don't Know		Building	Unknown	Unknown	Yes		
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
	Installation date after lead ban	No				Non-Lead	No	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
	Installation date after lead ban	No				Non-Lead	No	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
	Installation date after lead ban	No				Non-Lead	No	Don't Know		Single Family Residence	Unknown	Unknown			
	,	No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			

Customer-Owned Portion							Other Potential Sources of Lead			Additional Information to Assign Tap Monitoring Tiering				Lead Service Line Replacement (LSLR)	
Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	Ver		Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Lise	Does the Interior Building Plumbing Contain Copper Pipes with Lead Solder Installed Before Your State's Lead Ban (Generally 1986 - 1988)?	Current LCR	Date of System- owned LSLR	Date of Customer- owned LSLR
	Installation date after lead ban	No				Non-Lead	No	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			
		No				Unknown	Don't Know	Don't Know		Single Family Residence	Unknown	Unknown			